

ALLEGION HURRICANE ASSEMBLY APPROVAL LINKS v1/16/2024-- verify all assembly items/features in approval are offered in current Allegion brand price books before ordering

	TYPE	FBC 2023 listing site link	FBC 2023 Direct links to installation instructions (Steelcraft and Republic combined listings, also used now for TDI)	FBC DRAWING #	NOA 2023 (Steelcraft only)	TDI > FBC	DESCRIPTION
1	HVHZ Main Louver	FL12400-R14	1.DblLouvr--FL12400.1_R14_II_F882W-2D SS 2023-10-20.pdf	F882W-2D	use FBC HVHZ	x	Double Outswing with Louvers 35.7x76, max 8080 60psf
2	HVHZ Main listing		2.DblFlush--FL12400.2_R14_II_IRFD07 SS 2023-10-20.pdf	IRFD07	23-0821.19	x	Double Flush Outswing mort/cyl/rim/svr/cvr/3-pt 55-90psf
3	HVHZ Main listing		3.DblGlz--FL12400.3_R14_II_IRGD07 SS 2023-10-20.pdf	IRGD07	23-0821.17	x	Double Glazed Outswing mort/cyl/rim/svr/cvr/3-pt 50-90psf
4	HVHZ Main listing		4.SglFlush--FL12400.4_R14_II_IRFS07 SS 2023-10-20.pdf	IRFS07	23-0821.18	x	Single Flush Outswing mort/cyl/rim/svr/cvr/3-pt 55-100PSF
5	HVHZ Main listing		5.SglGlz--FL12400.5_R14_II_IRGS07 SS 2023-10-20.pdf	IRGS07	23-0821.16	x	Single Glazed Outswing mort/cyl/rim/svr/cvr/3-pt 50-100PSF
6	HVHZ Main Louver		6.SglLouvr--FL12400.6_R14_II_F882W-2S SS 2023-10-20.pdf	F882W-2S	use FBC HVHZ	x	Single Outswing Systems with Louvers 35.7x76, max 4080 60psf
7	HVHZ ELEV	FL1592-R12	7.ElevSdlitTrans--FL1592.1_R12_II_F975W SS 2023-10-20.pdf	F975W	23-0821.15	x	Outswing Elev Systems, Sidelts, Trans 3070/6070 60psf, 4070 50 psf
8	HVHZ Storefront	FL4622-R10	8.Storefront--FL4622.1_R10_II_F1107W SS 2023-08-16.pdf	F1107W	use FBC HVHZ	x	Light Elev System for use with Storefront entrance systems, 60psf
9	HVHZ Mortise 3070	FL3905-R12	9.MortInswingFI--FL3905.1_R12_II_776W-3 SS 2023-10-20.pdf	776W-3	23-0821.13	x	Single Flush Inswing Mort 3070 120PSF; 170 with SS Strike
10	HVHZ Mortise 3070		10.MortOutswgFI--FL3905.2_R12_II_776W-2 SS 2023-10-20.pdf	776W-2	23-0821.14	x	Single Flush Outswing Mort 3070 120PSF; 170 with SS Strike
11	HVHZ Falcon MA	FL16740-R8	11.FalcMAdbIFI--FL16740.1_R9_II_FMADF SS 2023-10-04.pdf	FMA-DF		x	Double Flush Mortise Falcon MA 4080/8080 50psf
12	HVHZ Falcon MA		12.FalcMASglFI--FL16740.1_R9_II_FMASF SS 2023-10-04.pdf	FMA-SF		x	Single Flush Mortise Falcon MA 4080/8080 50psf
13	HVHZ/Impact		13.CVC9949DblFI--FL16740.2_R9_II_F1049DF SS 2023-10-04.pdf	F1049DF		x	Double Flush CVC exit 98/9949, 33/3549 4080/8080 75psf
14	HVHZ/Impact		14.CVC9949SglFI--FL16740.2_R9_II_F1049SF SS 2023-10-04.pdf	F1049SF		x	Single Flush CVC exit 98/9949, 33/3549 4080/8080 75psf
15	HVHZ HCA		15.HCAdbIGlaz--FL16740.4_R9_II_F2334D SS 2023-10-04.pdf	F2334D		x	Double Glazed SVR exit 98/9927 70psf N6-6x30max light 31070 HCA
16	HVHZ HCA		16.HCAsglIGlaz--FL16740.4_R9_II_F2334S SS 2023-10-04.pdf	F2334S		x	Single Glazed SVR exit 98/9927 70psf N6-6HCA
17	HVHZ LevelE 3pt		17.LevelE-3ptDbl--FL16740.3_R9_II_F9300DF SS 2023-10-04.pdf	F9300DF		x	Double Flush 3-pt LM9300 3-Pt Level E 107PSF
18	HVHZ LevelE 3pt		18.LevelE-3ptSgl--FL16740.3_R9_II_F9300SF SS 2023-10-04.pdf	F9300SF		x	Single Flush 3-pt LM9300 3-Pt Level E 107PSF
19	HVHZ LevelE Exit	FL14022-R8	19.LevelE-ExitFI--FL14022.1_R8_II_F3580-1 SS 2023-08-16.pdf	3580-1		x	W598/9927 Sgl/Dbl Panic Level E 150psf (75 if water infiltration)
20	HVHZ Pos Lock exit	FL20736-R5	20.PosLokExitDbl--FL20736.1_R5_II_PL 2016-DF SS 2020-10-25.pdf	PL 2016-DF		x	Outswing pair 8080 Positive Lok panic exit
21	HVHZ Pos Lock exit		21.PosLokExitSgl--FL20736.2_R5_II_PL 2016-SF SS 2020-10-25.pdf	PL 2016-SF		x	Outswing single 4080 Positive Lok panic exit
22	EHPA ICC Flush	FL41734	22.EHPA.ICCflush--FL41734.1_R1_II_PWF001 SS 2022-10-26.pdf	PWF001			Flush Inswing/Outswing Hurricane/Tornado
23	EHPAx ICC Glazed		23.noEHPA.ICCGlaz--FL41734.2_R1_II_PWG001 SS 2022-10-26.pdf	PWG001			Glazed Inswing/Outswing Tornado
24	E330/Non-Impact	FL10356-R10	24.E330-FIDbl--FL10356.1_R10_II_FDDA330 SS 2023-10-20.pdf	FDDA330		x	Flush Outswing/Inswing Double Door (Non-HVHZ) E330
25	E330/Non-Impact		25.E330-FISgl--FL10356.2_R10_II_FSDA330 SS 2023-10-20.pdf	FSDA330		x	Flush Outswing/Inswing Single (Non-HVHZ) E330
26	E330/Non-Impact		26.E330-GISgl--FL10356.3_R10_II_GSDA330 SS 2023-10-20.pdf	GSDA330		x	Glazed Outswing/Inswing Single (Non-HVHZ) E330
27	E330/Non-Impact		27.E330-GIDbl--FL10356.4_R10_II_GDDA330 SS 2023-10-20.pdf	GDDA330		x	Glazed Outswing/Inswing Dbl (Non-HVHZ) E330
28	E330/Non-Impact		28.E330-LvrDbl--FL10356.5_R10_II_LDDA330 SS 2023-10-20.pdf	LDDA330		x	Louvered Outswing/Inswing Dbl Door Systems (Non-HVHZ) E330
29	E330/Non-Impact		29.E330-LvrSgl--FL10356.6_R10_II_LSDA330 SS 2023-10-20.pdf	LSDA330		x	Louvered Outswing/Inswing Sgl Door Systems (Non-HVHZ) E330
30	E330/Non-Impact	FL34907-R1	30.E330-Elev--FL34907_R1_II_RDF023 SS 2023-10-04.pdf	RDF023			Frame with Sidelites and Transom for 18ga Doors E330